

st Repor	t No.:	NGBHL24007670201	Date:	Dec 31, 2024	Page 1 of 3		
Client Name: SHANDONG SUNSMILE MUSICAL INSTRUMENT INC.							
Client Addr	ess: NO. 32 XINGI	HUA EAST ROAD, LIAOCHEN	NG, SHANE	OONG, CHINA			
Sample Description:		TWEETER					
	(ELECTRIC GUITAR, ELECTR GUITAR, MUSICAL INSTRUM (ITS, BANJO ,UKULELE, MAN MPLIFIER PARTS & ACCES rmation were provided by the o	ENT ACCE NDOLIN, G SORIES	SSORIES & PARTS,	GUITAR DIY		
SGS No.:	1	VBHL2412029032SD					
Sample Receiving Date:		Dec 24, 2024					
Testing Period:		Dec 24, 2024 ~ Dec 31, 2024					
Test Requested:		Select test(s) as requested by the client.					
Testing Performed:		Follow selected test(s) as requested by client.					
Test	Requirement				Conclusion		
1 Tota	I Fluorine Screenin	g			See Results		

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Ningbo Branch

Hayley Hong

Hayley Hong Approved Signatory



Verification: check.sgsonline.com.cn



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 83071443, or email: CN.Doccheck@esgs.com CN.Doccheck

No.1177, Lingyun Road, Hi-Tech Zone, Ningbo, Zhejiang, China 315040 t E&E (86-574)89070249 中国・浙江・宁波高新区凌云路1177号 邮编: 315040 tHL (86-574)89070271 tML (86-574)89070242 sgs.china@sgs.com

www.sgsgroup.com.cn



Test Report

No.: NGBHL24007670201

Date: Dec 31, 2024

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB24-0076702-0001.C001	Black plastic part

Remarks:

(1) 1 mg/kg = 1 ppm = 0.0001%

(2) MDL = Method Detection Limit

(3) ND = Not Detected (< MDL)

(4) "-" = Not Regulated

Total Fluorine Screening

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A1
Fluorine(F)	mg/kg	20	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.



No.1177, Lingyun Road, Hi-Tech Zone, Ningbo, Zhejiang, China 315040 tE&E (86-574)89070249 www.sgsgroup.com.cn 中国・浙江・宁波高新区凌云路1177号 邮编: 315040 tHL (86-574)89070271 tML (86-574)89070242 sgs.china@sgs.com





SGS authenticate the photo on original report only *** End of Report ***



No.1177, Lingyun Road, Hi-Tech Zone, Ningbo, Zhejiang, China 315040 t E&E (86–574)89070249 www.sgsgroup.com.cn 中国•浙江•宁波高新区凌云路1177号 邮编: 315040 t HL (86–574)89070271 t ML (86–574)89070242 sgs.china@sgs.com